



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: July 6, 2009

Reviewed: LR

Mine Name: Little Mountain	Permit Number: M0450005
Operator Name: Utah Portland Cement	Inspection Date: 05/26/2009
Inspector(s): Leslie Heppler	Time: 3:30 pm
Other Participants: Brett Gregory & Vicky Dyson	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$69,800 **Bond Renewal Date** 08/21/2007 **Permit fee:** \$500 due – invoice sent out 06/20/2009

Purpose of Inspection: Routine Annual Inspection, last inspection date 03/15/2007

Inspection Summary: Mine status is listed as Active. No recent mining is evident. Mine Site is currently used as a shooting range.

Conclusions and Recommendations: The bond renewal date is past due for escalation. The Operator should reclaim the area or update the Notice of Intention and a bond escalation should be done to match current pricing for reclamation.

Inspector's Signature

lah:vs

cc Bryan Lane

O:\M045-Tooele\M0450005-LittleMountainQuarry\inspections\insp-05262009.doc



View from the north on entrance road



Highwall



Highwall



Highwall